

336 WEST FRONT STREET P.O. BOX 4004 BURLINGTON, NORTH CAROLINA 27215 PHONE (336) 227-7710 • FAX (336) 227-1175

www.diversifiedtestinglabs.com

ORLDWIDE SERVICE

DIVERSIFIED ESTING LABORATORIES, INC.

"We Test Per Your Request"

December 7, 2016

Ms. Barbara Crane RAXON FABRICS P.O. Box 1698 Henderson, NC 27536

Reference: Laboratory Test Report Lab Identification No. 22779 Invoice No. 53932

Dear Ms. Crane:

One (1) fabric sample, identified as **PATTERN HESTAN TEST # 380**, was received and tested in accordance with the California Technical Bulletin 117-2013, Section 1, Cover Fabric Test. The results are as follows:

Test Results Char 10mm 12mm 13mm

The sample submitted **meets** the requirements of the above standard. There were obvious ignitions or smoldering after 45 minutes on all three specimens tested.

If there are any questions or when we can be of further assistance, please let us know.

Sincerely,

Brian S. Dement

BSD/mr

