



Date of Issue: 5/4/2021 Report Number: 21-000191

Revision Number:2

Date Order Received: 01/21/2021

For the Account of: Vescom, B.V.

Sint Jozestraat 20 5753 Av Duerne

Client's Identification:

Avon

None

CERTIFICATE OF TESTING

TEST PERFORMED: Resistance to Slippage of Yarns in Woven Fabrics Using a Standard Seam ASTM D4034-92

TEST RESULTS

Specimen	Warp Yarn Slippage (lbf)	Type of Failure	Specimen	Fill Yarn Slippage (lbf)	Type of Failure
1	113.0	SB	1	86.7	SB
2	110.0	SB	2	83.0	SB
3	121.0	SB	3	85.1	SB
4	114.0	SB	4	65.7	SB
5	97.0	SB	5	72.8	SB
Avg. Warp	111.0		Avg. Fill	78.5	

ABBREVIATIONS USED

SB Seam broke before 1/4" slippage - Results should reflect this

SS 1/4" slippage occurred - Note: Actual slippage of yarns is visible

FB Fabric broke before 1/4" slippage - Note: Actual breakage is visible

NOTES

Equipment Used: Tinius Olson H5KT Universal Testing Machine

Seam Description:

Seam TypeStandard LockstitchStitches per Inch 7 ± 0.5 stitches per inch

Needle Used Size 22 NM: 140, 135x17 ball point needle

Thread Nymo EX Bonded Nylon thread; 5x is used for the bobbin and 8x is used for the needle

ACCEPTANCE CRITERIA

A.C.T. Standard Acceptance Criteria
Upholstery 25 lbs. Minimum

CERTIFICATION I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.

Authorized Signature

Date Order Completed: 01/22/2021

553 76th Street, Byron Center, MI 49315

P: 616-559-6123 E: testlab@applied-lab.com

Page 1 of 1