



Report Number: 18-001607

Revision Number:1

Date Order Received: 03/15/2018

For the Account of: Vescom America Inc.

2289 Ross Mill Road Henderson, NC 272537

Client's Identification: Noss 7058 Test #606

# **CERTIFICATE OF TESTING**

**TEST PERFORMED:** Pilling Resistance and Other Related Surface Changes of Textile Fabrics: Brush Pilling Tester ASTM D3511/D3511M-16

### **TEST RESULTS**

	Rating
Left	5.0
Center	5.0
Right	5.0
Average Rating	5.0

#### **RATING SYSTEM**

Class 5.0 No Pilling
Class 4.0 Slight Pilling
Class 3.0 Moderate Pilling
Class 2.0 Severe Pilling
Class 1.0 Very Severe Pilling

## **NOTES**

**Test Conditions:** 70 ±4°F, 65 ±5% Relative Humidity

Sampling Method: As Received
Viewing Apparatus: Macbeth Lightbooth

Viewing Option: 45 degree

Rating Standard: ADJD3512 Photographic Standards
Running Times: 4 minutes brushing / 2 minutes pilling

## **ACCEPTANCE CRITERIA**

A.C.T. Standard: Acceptance Criteria
Upholstery Class 3 minimum

**CERTIFICATION** I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.

Authorized Signature

Authorized Signature Date Order Completed: 03/23/2018

553 76th Street, Byron Center, MI 49315

P: 616-559-6123 E: testlab@applied-textiles.com

Page 1 of 1