

Lightfastness Textile Wallcovering VI

Testing as per ISO. 105 B method 2

Testresults are based upon 216 hours of exposure. Test was stopped at 216 hours.

Location test

Tapetex BV, Helmond, Holland

Testing machinery

Heraeus original Hanau Xenotest 150S

Standard blue scale 0 - 8

Humidity 65%, Blackpanel temperature 45° Celsius

Testing completed

February 2015

| design | | result | design | | result |
|---------------|------------------|---------------|-----------------|-----------------|---------------|
| Chandra | 251250 - 251251 | 7 | Chateau Chinon | 251340 - 251344 | 7 |
| silk | 251252 - 251258 | 6 | silky | | |
| | 251259 | 4 | | | |
| | 251260 - 251262 | 7 | Chennai | 251350 - 251354 | 7 |
| | 251263 | 6 | silky | | |
| | 251264 | 7 | | | |
| | 251265 | 5 | New Voyages | 251360 - 251364 | 7 |
| | 251266 - 251267 | 6 | silky | | |
| | 251268 | 3 | | | |
| | 251269 | 6 | Madurai | 251370 - 251379 | 7 |
| | 251270 - 251271 | 7 | silky | | |
| | 251272 - 251273 | 6 | | | |
| | 251274 - 25 1276 | 5 | Deep Spaces | 251380 - 251384 | 7 |
| | 251277 | 6 | silky | | |
| | 251278 | 4 | | | |
| 251279 | 6 | Kerala | 251390 - 251394 | 5 | |
| | | | silky | | |
| Shambala | 251280 | 6 | | | |
| silk | 251281 - 251282 | 7 | Princess Lace | 251400 - 251404 | 6 |
| | 251283 | 6 | silky | | |
| | 251284 | 5 | | | |
| Ayesha | 251290 | 3 | | | |
| silk | 251291 | 7 | | | |
| | 251292 | 6 | | | |
| | 251293 | 4 | | | |
| | 251294 | 6 | | | |
| Lost Horizon | 251300 - 251301 | 7 | | | |
| silk | 251302 | 5 | | | |
| | 251303 | 6 | | | |
| | 251304 | 5 | | | |
| | | | | | |
| Saray | 251310 - 251317 | 6 | | | |
| silk | 251318 - 251319 | 5 | | | |
| Tabaz | 251320 - 251324 | 6 | | | |
| silk | | | | | |
| Sagar | 251330 - 251331 | 7 | | | |
| silk | 251332 - 251333 | 6 | | | |
| | 251334 | 5 | | | |